T



THE STATE OF NEW HAMPSHIRE DEPARTMENT OF TRANSPORTATION July 25, 2019

Like

Victoria F. Sheehan
Commissioner
Leslie Palmer
Webster Town Administrator
945 Battle Street
Webster, NH 03303

Post-it® Fax Note	7671	Date 7 25/19 # of pages 6
To Leolie Palm	ner	From C. R. Willeke
Co./Dept.)elaster	T.A.	CO. NH DOT
Phone # 648- 2	272	Phone # 271-6472
Fax# 618-6	055	Fax# 271-8093

RE: CRITICAL BRIDGE DEFICIENCY

Webster Bridge #066/113 - White Plains Road over Meadow Brook

Dear Leslie:

During a recent underwater bridge inspection, the following critical deficiency was noted:

This structure has continued to deteriorate steadily since it was added to the Municipal Red List in 2005. The corrugated steel culverts have widespread areas of heavy corrosion and pitting with many areas rusted through, exposing the gravel fill. This deterioration is concentrated at and below the normal water elevation. In a few areas, the corrosion, pitting, and holes result in section losses exceeding 90%. Minor settlement in the roadway asphalt was noted above the areas of the heaviest section losses. Additionally, there is heavy debris accumulation (beaver dams) in the upstream opening of all three pipes.

The bridge is currently posted "E-2".

This deterioration has reduced the safe calculated live load capacity, resulting in a required posting of "WEIGHT LIMIT 3 TONS" and "PASSENGER CARS ONLY" for the short-term. However, without action, this bridge will likely require a closure in the near future. The municipality should monitor this structure closely for signs of further deterioration. Due to the extensive nature of the deterioration, slip-lining or complete replacement may be the only viable remedial actions.

<u>Due to this structural deficiency this bridge is included on the Department's Municipal Red List of deficient bridge structures. It is in need of complete replacement or extensive rehabilitation to continue to carry all legal loads.</u>

We are enclosing a copy of the inspection report and photos for your use. Please keep us informed of any actions taken by the Town so we can keep our records current. If you have any questions or comments, please contact us.

Sincerely,

C. R. Willeke, P.E.

Municipal Highways Engineer

C.R. Willeh

Bureau of Planning and Community Assistance

Telephone: (603) 271-6472 / Fax: (603) 271-8093

CRW Enclosure

cc: Webster Road Agent

Commissioner, Department of Education

S:\Planning\Community Assistance\1-Municipalities\Webster\Bridge Insp\Critical 066-113 7-25-19.doc

JOHN O. MORTON BUILDING • 7 HAZEN DRIVE • P.O. BOX 483 • CONCORD, NEW HAMPSHIRE 03302-0483 TELEPHONE: 603-271-3734 • FAX: 603-271-3914 • TDD: RELAY NH 1-800-735-2964 • INTERNET: WWW.NHDOT.COM

New Hampshire Department of Transportation

Bridge Inspection Report

NBI Structure Number: 026800660011300

Webster 066/113

Date of Inspection: 07/15/2019

Date Report Sent: 07/24/2019

Owner: Municipality

Bridge Inspection Group: B-Team Bridge Maintenance Crew: OTHER WHITE PLAINS ROAD

over

MEADOW BROOK

Existing Bridge Section Bureau of Bridge Design

☑ Critical Deficiency Status ADDITIONAL CORROSION-RELATED DETERIORATION HAS REDUCED THE LIVE LOAD CAPACITY. POSTING REQUIRED.

Recommended Postings:

Weight: Weight Limit 3 Tons and Passenger Cars Only

CURRENTLY POSTED "E-2". This bridge requires "Weight Limit 3 Tons" and "Passenger Cars

Only" signs.

Width: Not Required

✓ Width Sign OK

☐ Weight Sign OK

Primary Height Sign Recommendation: None

Optional Centerline Height Sign Rec: None

Clearances:

(Feet)

Over: 99.99

Under:

✓ Height Sign OK

Route: 99.99

0.00

Condition:

Red List Status: Municipal Redlist

Deck: N N/A (NBI)

Superstructure: N N/A (NBI)

Substructure: N N/A (NBI)

Culvert: 2 Critical

Sufficiency Rating: 40 %

Structure Type and Materials:

Number of Main Spans:

0

Number of Approach Spans:

Main Span Material and Design Type

Steel/Culvert

Bridge Rail: N/A or not required

Rail Transition: N/A or not required

Bridge Approach Rail: Meets Standards

Approach Rail Ends: Substandard

NH Bridge Type: MP (Metal Pipe)

Deck Type: N/A (NBI)

Wearing Surface: N/A (no deck (NBI))

Membrane: N/A (no deck (NBI))

Deck Protection: N/A (no deck (NBI))

Curb Reveal: Not Measured

Plan Location:

Total Bridge Length:

13.0 ft

Right Curb/Sidewalk Width:

0.0 ft

Total Bridge Width:

0.0ft

Median: No median

Bridge Skew: 0.00°

Year Built/Rebuilt: 1930/1989

Bridge Dimensions:

Length Maximum Span:

Left Curb/Sidewalk Width:

0.0 ft

Width Curb to Curb:

0.0 ft 18.0 ft

4.0ft

Approach Roadway Width:

(W/Shoulders)

NHDOT 008 Inspection

Webster 066/113

Printed on: 7/23/2019 2:04:28 PM

Page 1 of 5

New Hampshire Department of Transportation

Bridge Inspection Report

NBI Structure Number: 026800660011300

Existing Bridge Section Bureau of Bridge Design

Webster 066/113

Element Details (see disclaimer below)

No.	Description	Material Notes and Condition Notes:
215	Reinforced Concrete Abutment	CONCRETE HEADWALL HAS MINOR SPALLS AT BASE AND UNDERMINED IN AREAS.
^L 1080	Delamination/Spall/Patched Area	CONCRETE HEADWALL HAS MINOR SPALLS AT BASE.
Ĺ 6000	Scour	SCOUR ON DOWNSTREAM END WITH UP TO 6 in. PENETRATION IN SEVERAL AREAS.
217	Masonry Abutment	VOIDS AROUND INLET AND IN HEADWALL. STONE SETTLED AT NORTHWEST WING.
└ 1640	Masonry Displacement	VOIDS AROUND INLET BETWEEN PIPES WITH UP TO 16" OF PENETRATION. VOIDS IN HEADWALL.
L 4000	Settlement	STONE SETTLED AT NORTHWEST WING.
240	Steel Culvert	4' DIAMETER. THREE (3) SPIRAL MP- 2 2/3 in. X 1/2 in. WITH 3.5' OF COVER. SAGS IN ROOFLINE OF ALL THREE PIPES. UPSTREAM JOINTS SEPARATED UP TO 2.5 in HOLED AREAS IN PIPE # 1 & 3 WITH FILL EXPOSED. MINOR TO LIGHT SCALE AND RUST IN PIPE # 2. ASPHALT IS SETTLED OVER HOLED AREAS AT SOUTHWEST. DEBRIS IN PIPES # 2 & 3 AT MIDSPAN. DAMAGED AREAS AT INLET END OF ALL PIPES.
^L 1000	Corrosion	MINOR TO LIGHT SCALE AND RUST IN PIPE #2. PIPE #1- 10' FROM SOUTH END, HOLED IN A 6' SECTION WITH UP TO 90% SECTION LOSS; 17' FROM SOUTH END, HOLED THROUGH IN A 1' AREA, 100% SECTION LOSS. PIPE #3- HOLED THROUGH IN A 8 in. AREA WITH FILL EXPOSED, MIDSPAN. ALL THREE PIPES HOLED AT INLET INVERT AND SIDES FROM RUST AND DAMAGE.
^L 1020	Connection	UPSTREAM JOINTS SEPARATED UP TO 2.5 in
^L 1900	Distortion	SAGS IN ROFFLINE OF PIPE # 1.
[[] 6000	Scour	DEBRIS IN PIPES # 2 & 3, MIDSPAN.
L7000	Damage	INLET ENDS (NORTH) OF ALL THREE PIPES HAVE DAMAGE CAUSED BY BEAVER DAM REMOVAL.

Element States (see disclaimer below)

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
215	Reinforced Concrete Abutment	26	ft	62%	38%	0%	0%
1080	Delamination/Spall/Patched Area	5	ft	0%	100%	0%	0%
^L 6000	Scour	5	ft	0%	100%	0%	0%
217	Masonry Abutment	26	ft	0%	100%	0%	0%
1640	Masonry Displacement	10	ft	0%	100%	0%	0%
-4000	Settlement	5	ft	0%	100%	0%	0%
240	Steel Culvert	121	ft	0%	0%	0%	100%
1000	Corrosion	80	ft	0%	0%	0%	100%
1020	Connection	5	ft	0%	0%	0%	100%
1900	Distortion	10	ft	0%	0%	0%	100%
6000	Scour	10	ft	0%	0%	0%	100%
7000	Damage	9	ft	0%	0%	0%	100%

Element Disclaimer: NHDOT is transitioning from CoRe elements to AASHTO elements. The AASHTO element data shown above is the product of the automated element migration routine from the AASHTOWare BrM software. This migrated data has undergone limited field verification. Adequate quality control of this element data is not expected to be achieved until the conclusion of the 2020 inspection season. Please utilize element data with caution.

Bridge Notes:

ADDED TO THE MUNICIPAL RED LIST ON 8/31/05. ROAD NAME CHANGE FROM "SCHOODAC ROAD" TO "WHITE PLAINS ROAD". ONLY 16" OF FREEBOARD CAUSED BY BEAVER DAM DOWNSTREAM, 12/8/2015.

18" OF FREEBOARD, 11/28/2016, 10/13/2017.

NHDOT 008 Inspection

Printed on: 7/23/2019 2:04:28 PM

Webster 066/113

New Hampshire Department of Transportation

Bridge Inspection Report

NBI Structure Number: 026800660011300

Existing Bridge Section Bureau of Bridge Design

Webster 066/113

Inspection History

Inspection	Inspector	Inspection Type(s) Performed				Major Element Ratings				Red	n	
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	Posting	
07/15/2019	NBG	V	V		V	N	N	N	2	V	3 Tons PCO	
10/30/2018	MHC	V	V			N	N	N	3	V	E-2	
10/13/2017	MHC	V	V			N	N	N	3	V	E-2	
09/05/2017	NBG				V	N	N	N	3	V	E-2	
11/28/2016	MHC	\checkmark	V			N	N	N	3	V	E-2	
12/08/2015	MHC	V	V			N	N	N	3	V	E-2	
12/10/2014	MHC	V	V			N	N	N	3	V	E-2	
09/30/2013	NJL	✓	V			N	N	N	3	V	E-2	
12/18/2012	KLM	V	V			N	N	N	4	V	E-2	
09/20/2011	MHC	V	V			N	N	N	4	V	E-2	
09/24/2010	KLM	V	V			N	N	N	4	V	E-2	
01/16/2009	RLM	\checkmark	V			N	N	N	4	V	E-2	
10/11/2007	JEL	V	V			N	N	N	4	V	E-2	
10/17/2006	JEL	V	V			N	N	N	4	V	E-2	
08/31/2005	JEL	V	V			N	N	N	4	V	E-2	
07/07/2003	FNM	\mathbf{Z}	V			N	N	N	5		E-2	
02/02/2001	FNM	V	V			N	N	N	6		E-2	
01/12/1999	RLM	\mathbf{Z}	V			N	N	N	6		E-2	
09/01/1996		V	V			N	N	N	6		E-2	
10/01/1994		\mathbf{V}	V			N	N	N	7		E-2	
08/01/1992		V	V			N	N	N	N	П	E-2	

Inspection Frequency (mo.)								
NBI Elem FCM U/W								
16	16	N/A	16					

					П		T	Т	7
}		2019	7/24/19			POSTING	HS 4.1	S	
WEBSTER	066/113	DATE: 7/23/2019	DATE: 7/2			SINGLE LANES LOADED (Y OPERATING	HS 4.5	Metric Tons 6.7	
		NBG	377	MEADOW BROOK	ACITY (HS Tons)	INVENTORY	HS 2.7	1 Tons 7.4 4.3	
TOWN:	BRIDGE NUMBER:	RATED BY:	CHECK BY:	OVER: MEAD	AVAILABLE CAPACITY (HS Tons)	DED	HS 3.7	English Tons 64. (Op.) 7.4 66. (Inv.) 4.3	
						IPLE LANES LOA OPERATING	HS 4.1	Aethod LF LF	
		UNKNOWN				INVENTORY	HS 2.4	Rating Method (Op.) 63. LF (Inv.) 65. LF	X 50
		ł	UNKNOWN		S Tons)	MULTIPLE	HS 15.4		William Charles
		DESIGN METHOD:	PLAN FILE:		REQUIRED CAPACITY (HS Tons)	SINGLE MULTIP UNIT UNIT	HS 18.5	ALY"	GOULAS, JR. MICHOLAS GOULAS, JR. MAINTHINGS ON 12056 P. 25.2019
				AD	REQUIR	CURRENT LEGAL LOADS	HS 16.8	"WEIGHT LIMIT 3 TONS" & "PASSENGER CARS ONLY"	PROPERTY OF PROPERTY OF THE PR
	RY	UNKNOWN	LOAD FACTOR	WHITE PLAINS ROAD	LONGITUD.	SPAN LENGTH	\$-0.	"WEI	÷
Form 4 N.H. D.O.T.	BRIDGE CAPACITY SUMMARY	DESIGN LOAD:	RATING METHOD:	ROUTE:	COTT A C	KA1ED MEMBER	Corrugated Metal Pipes (3-6" cover, 90%+ losses)	RECOMMENDED POSTING:	

WEBSTER 066/113 WHITE PLAINS ROAD over MEADOW BROOK

Owner: Municipality Inspection Team: B

Monday, July 15, 2019


DOWNSTREAM ELEVATION. NOTE DEBRIS BLOCKAGE OF BARREL (TYPICAL OF ALL THREE PIPES).



X018 04

Monday, July 15, 2019


TYPICAL HEAVY RUSY AND SECTION LOSSES ON PIPE WALL.



X018 05

Monday, July 15, 2019

TYPICAL HEAVY RUSY AND SECTION LOSSES ON PIPE WALL. NOTE GRAVEL FILL EXPOSED.



X018 06